



Aviation Investigation Notification

Location:	Libby, MT	Accident Number:	WPR26LA099
Date & Time:	February 4, 2026, 20:45 Local	Registration:	N407VS
Aircraft:	BELL HELICOPTER TEXTRON CANADA BHT407	Injuries:	3 None
Flight Conducted Under:	Part 135: Air taxi & commuter - Non-scheduled - Air Medical (Medical emergency)		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	BELL HELICOPTER TEXTRON CANADA	Registration:	N407VS
Model/Series:	BHT407	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	A L E R T Kalispell Regional Medical Center Inc	Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Designator Code:	CXVA		

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Night
Observation Facility, Elevation:	K65S,2333 ft msl	Observation Time:	20:35 Local
Distance from Accident Site:	36 Nautical Miles	Temperature/Dew Point:	2°C /2°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	30.42 inches Hg	Type of Flight Plan Filed:	CVFR
Departure Point:	Kalispell, MT (MT28)	Destination:	Libby, MT (None)

Wreckage and Impact Information

Crew Injuries:	3 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	48.392012,-115.54532 (est)

Administrative Information

Investigator In Charge (IIC):	Mills, Grant
Additional Participating Persons:	Charles Clark; Federal Aviation Administration; Helena, MT
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.